

ELEV 979

NZJO

NON-CERTIFICATED


# ROTORUA HOSPITAL

## HELIPORT

ROTORUA TOWER: 121.2


ROTORUA ATIS: 128.8

UNATTENDED: 121.2



NZJO-D

Changes from 18 NOV 10: NZLF heliport removed.



Heliport located within Rotorua CTR/D.  
 Noise abatement — do not overfly hospital.  
 For Non-Performance Class 1 helicopters,  
 specific procedures apply — contact the  
 BayTrust Rescue Pilot for details.

S 38 07 55 E 176 14 48\*

**Effective: 4 FEB 16**

© Civil Aviation Authority

# ROTORUA HOSPITAL HELIPORT

**FATO/TLOF**

	SIZE	SFC	STRENGTH	MARKINGS
FATO	14 m x 32 m			
TLOF	13 m x 13 m	Conc		Standard

**LIGHTING**

FATO: Floodlighting

TLOF: Perimeter — orange/blue. Lights remain on from ECT to MCT.

WDI: Light linked to perimeter lighting

**FACILITIES**

Fuel: Z Energy Z Card — Jet A1

**SUPPLEMENTARY**Operator: Lakes District Health Board, Rotorua Hospital, Private Bag 3023, Rotorua.  
Tel (07) 349 7915 Fax (07) 349 7942

Available for limited use subject to the prior agreement of the operator.

Prior to landing contact BayTrust Rescue, Tel (027) 499 9117 — duty pilot (H24).

Visiting aircraft to park on the TLOF area.

A second aircraft may park in front of the hangar doors but the pilot is to remain with the aircraft and shall be ready to move the aircraft clear for the BayTrust Rescue helicopter.