

ELEV 760


TE PUIA SPRINGS HOSPITAL

NZJP

NON-CERTIFICATED


HELIPORT

UNATTENDED: 119.1



NZJP-A

Changes from 4 SEP 03: Helipod size increased, trees removed, MAG VAR.



Heliport at NW corner of hospital.
Obstacles: Low hedge to north and west of FATO.

S 38 03 16 E 178 18 16*

Effective: 7 FEB 13

TE PUIA SPRINGS HOSPITAL

© Civil Aviation Authority

HELIPORT

FATO/TLOF

	SIZE	SFC	STRENGTH	MARKINGS
FATO	Diameter 20m	Gr*		
TLOF	6m x 6m	Conc		Standard

*Slopes away to north and west of TLOF.

Maximum helicopter size 13m overall length.

LIGHTING

FATO: Floodlighting

WDI

FACILITIES

Dry powder fire extinguisher located at entrance to helipad.

SUPPLEMENTARY

Operator: Te Puia Springs Hospital, PO Box 1, Te Puia Springs.
Tel (06) 864 6803 Fax (06) 864 6891

Available for general use without the permission of the operator.