

ELEV 100


NZOT

NON-CERTIFICATED

**OTAKI****AERODROME**

UNATTENDED: 118.3

PARAPARAUMU FLIGHT SERVICE: 118.3



1. **Caution:** Turbulence and windshear can be expected in crosswinds.
2. **Caution:** Mowing of runways and operational areas may take place at any time.
3. Pine trees at each end of displaced thresholds of both runways.
4. Surface uneven in places. Taxi on centre of runway.
5. Due to the close proximity to Mandatory Broadcast Zone B680, pilots are advised to radio Paraparaumu Flight Service 118.3 MHz for traffic information prior to arrival or departure.
6. Co-existing RWY designators exist at Paraparaumu AD (10 NM SW of aerodrome). Aircraft operating in the Otaki circuit are advised to call using "northern vector" or "southern vector" on 118.3 MHz to avoid confusion with the Paraparaumu AD circuit.

S 40 47 01 E 175 09 04\*

**Effective: 18 SEP 14**

© Civil Aviation Authority

**OTAKI**  
**AERODROME**

NZOT

**OPERATIONAL DATA****RWY**

RWY	SFC	Strength	Gp	Slope	ASDA	Take-off distance			LDG DIST
						1:20	1:30	1:40	
16 16	Gr	ESWL 9080	5 6	0.73U		730			730
34 34	Gr	ESWL 9080	6 5	0.73D		730			730

**LIGHTING**

Nil

**FACILITIES**

Toilet located behind Timber Hangar

**SUPPLEMENTARY**

Operator: Otaki Airstrip Limited  
 Manager Rob Kofoed, 196 Rahui Road, Otaki RD3  
 Tel (06) 364 6154 Fax (06) 364 6194 Cell (027) 536 4614  
 Email: rob.kofoed@xtra.co.nz

Landing and overnight fees payable. Additional cost for invoiced charges.

Available for limited use subject to prior agreement of the operator.