


ELEV 1220

NZTN

NON-CERTIFICATED

**TURANGI
AERODROME**

UNATTENDED: 119.1



Changes from 4 APR 13: Runway width reduced.

1. Circuit: RWY 02 — Left hand
RWY 20 — Right hand
2. Parking area at southern end — apron in front of clubhouse.
3. **CAUTION:**
 - Severe turbulence can be expected in strong southwest wind conditions,
 - Northern end of aerodrome subject to flooding after heavy rain.
4. Telephone on exterior of clubhouse (07) 386 5650 (Mountain Air Ltd).

S 38 58 06 E 175 48 49*

Effective: 19 SEP 13

© Civil Aviation Authority

**TURANGI
AERODROME**

NZTN

OPERATIONAL DATA**RWY**

RWY	SFC	Strength	Gp	Slope	ASDA	Take-off distance			LDG DIST
						1:20	1:30	1:40	
02	Gr(f)	ESWL 820	3 5	0.72D		610			768
20	Gr(f)	ESWL 820	5 3	0.72U		768			610

LIGHTING

Nil

FACILITIES

Nil

SUPPLEMENTARY

Operator: Taupo Airport Authority, RD2, Taupo
 Tel (07) 378 7771 Fax (07) 378 7776
 Email: admin@taupoairport.co.nz

D Available for general use.

D Landing fees are payable at the Turangi Aero Club clubhouse:

I Private operators — \$5.00

Commercial operators — \$10.00

Additional \$10.00 if invoiced.

No charge for Turangi Aero Club members for private operations.

D