


ELEV 5

NZTR

NON-CERTIFICATED

TE ARAROA
AERODROME

UNATTENDED: 119.1



Changes from 7 OCT 21: Note 3 wind shear caution added.

1. **Caution:** Terrain rises to SE.
2. **Caution:** Departures off RWY 10 due downdraughts in southerly wind conditions. Northerly turn after departure recommended in these conditions.
3. **Caution:** Possible wind shear on final approach to RWY 10 in light southerly conditions.

S 37 37 45 E 178 20 51*

Effective: 12 JUN 25

© Civil Aviation Authority

TE ARAROA
AERODROME

RWY

RWY	SFC	Strength	Gp	Slope	ASDA	Take-off distance			LDG DIST
						1:20	1:30	1:40	
10	Gr(f)	6350	6	Nil	760	760			760
28	Gr(f)	6350	6	Nil	760	760			760

LIGHTING

Nil

FACILITIES

Nil

SUPPLEMENTARY

Operator:

Richard Clarke
Te Rimu Trust
Email: richard@terimu.co.nz
Tel 027 443 8597

Landing fees:

Honesty box, online payment and koha (donation) can be made to bank
account 02-0636-0216835-000

Available for general use